



VC 101

(K 50-H 1104/A 50-2123 B)

kann als Ersatzregler für nachstehende Typen verwendet werden:

| | | | | | | | | |
|----------|----------|----------|-----------|-----------|-----------|-------------|-------------|-------------|
| A 50-104 | A 50-171 | A 50-239 | A 50-323 | A 50-2028 | A 50-2216 | A 52-145 | K 50 L 3248 | K 50 P 1375 |
| A 50-108 | A 50-173 | A 50-240 | A 50-324 | A 50-2029 | A 50-2217 | A 52-147 | K 50 L 3266 | K 50 P 1380 |
| A 50-110 | A 50-174 | A 50-241 | A 50-525 | A 50-2034 | A 50-2274 | A 52-155 | K 50 L 3272 | K 50 P 1381 |
| A 50-113 | A 50-177 | A 50-242 | A 50-529 | A 50-2035 | A 50-2275 | A 52-156 | K 50 L 3291 | K 50 P 1382 |
| A 50-114 | A 50-179 | A 50-243 | A 50-534 | A 50-2037 | A 50-2277 | A 52-157 | K 50 L 3292 | K 50 P 1393 |
| A 50-115 | A 50-180 | A 50-244 | A 50-536 | A 50-2040 | A 50-2280 | A 52-158 | K 50 L 3294 | K 50 P 1394 |
| A 50-116 | A 50-186 | A 50-250 | A 50-539 | A 50-2046 | A 50-2284 | A 52-159 | K 50 L 3300 | K 50 P 1395 |
| A 50-117 | A 50-189 | A 50-251 | A 50-541 | A 50-2056 | A 50-2291 | A 52-160 | K 50 L 3305 | K 50 P 1398 |
| A 50-118 | A 50-192 | A 50-242 | A 50-543 | A 50-2059 | A 50-2297 | A 52-163 | K 50 L 3306 | K 50 P 1405 |
| A 50-119 | A 50-194 | A 50-253 | A 50-544 | A 50-2060 | A 50-2298 | A 52-164 | K 50 L 3310 | K 50 P 1409 |
| A 50-121 | A 50-195 | A 50-255 | A 50-547 | A 50-2061 | A 50-2301 | A 52-166 | K 50 L 3331 | K 50 P 1410 |
| A 50-122 | A 50-196 | A 50-258 | A 50-548 | A 50-2064 | A 50-2304 | A 52-175 | K 50 L 6507 | K 50 P 1415 |
| A 50-123 | A 50-197 | A 50-263 | A 50-549 | A 50-2066 | A 50-2307 | A 52-179 | K 50 P 1110 | K 50 P 1422 |
| A 50-124 | A 50-199 | A 50-264 | A 50-551 | A 50-2069 | A 50-2307 | A 52-183 | K 50 P 1147 | K 50 P 1423 |
| A 50-125 | A 50-200 | A 50-267 | A 50-552 | A 50-2070 | A 50-3000 | A 52-2012 | K 50 P 1148 | K 50 P 1427 |
| A 50-126 | A 50-201 | A 50-268 | A 50-555 | A 50-2072 | A 50-3001 | | K 50 P 1149 | K 50 P 1438 |
| A 50-128 | A 50-202 | A 50-271 | A 50-556 | A 50-2078 | A 50-7008 | K 50 H 2011 | K 50 P 1170 | K 50 P 1443 |
| A 50-129 | A 50-206 | A 50-272 | A 50-559 | A 50-2082 | A 52-100 | K 50 H 2037 | K 50 P 1181 | K 50 P 1444 |
| A 50-133 | A 50-209 | A 50-274 | A 50-561 | A 50-2083 | A 52-101 | K 50 H 2039 | K 50 P 1183 | K 50 P 1447 |
| A 50-134 | A 50-210 | A 50-278 | A 50-1001 | A 50-2100 | A 52-106 | K 50 H 2060 | K 50 P 1213 | K 50 P 1448 |
| A 50-136 | A 50-213 | A 50-279 | A 50-2000 | A 50-2103 | A 50-109 | K 50 H 2062 | K 50 P 1221 | K 50 P 1450 |
| A 50-137 | A 50-126 | A 50-280 | A 50-2002 | A 50-2107 | A 52-110 | K 50 H 2063 | K 50 P 1222 | K 50 P 1451 |
| A 50-138 | A 50-217 | A 50-281 | A 50-2003 | A 50-2110 | A 52-1111 | K 50 H 2064 | K 50 P 1233 | K 50 P 1452 |
| A 50-139 | A 50-220 | A 50-288 | A 50-2005 | A 50-2111 | A 52-112 | K 50 H 2067 | K 50 P 1234 | K 50 P 1459 |
| A 50-140 | A 50-221 | A 50-290 | A 50-2007 | A 50-2115 | A 52-113 | K 50 H 2068 | K 50 P 1264 | K 50 P 1460 |
| A 50-142 | A 50-222 | A 50-291 | A 50-2008 | A 50-2118 | A 52-116 | K 50 L 3011 | K 50 P 1265 | K 50 P 1476 |
| A 50-144 | A 50-223 | A 50-292 | A 50-2015 | A 50-2119 | A 52-117 | K 50 L 3038 | K 50 P 1272 | K 50 P 1477 |
| A 50-145 | A 50-224 | A 50-293 | A 50-2016 | A 50-2131 | A 52-119 | K 50 L 3067 | K 50 P 1276 | K 50 P 1480 |
| A 50-147 | A 50-225 | A 50-295 | A 50-2017 | A 50-2149 | A 52-120 | K 50 L 3107 | K 50 P 1278 | K 50 P 1482 |
| A 50-151 | A 50-226 | A 50-297 | A 50-2019 | A 50-2200 | A 52-121 | K 50 L 3117 | K 50 P 1292 | K 50 P 1483 |
| A 50-156 | A 50-227 | A 50-299 | A 50-2020 | A 50-2204 | A 52-122 | K 50 L 3126 | K 50 P 1312 | K 50 P 1484 |
| A 50-157 | A 50-228 | A 50-300 | A 50-2021 | A 50-2205 | A 52-127 | K 50 L 3128 | K 50 P 1319 | K 50 P 1502 |
| A 50-158 | A 50-230 | A 50-301 | A 50-2022 | A 50-2206 | A 52-129 | K 50 L 3143 | K 50 P 1343 | K 50 P 1504 |
| A 50-160 | A 50-233 | A 50-309 | A 50-2023 | A 50-2208 | A 52-134 | K 50 L 3144 | K 50 P 1344 | K 50 P 1517 |
| A 50-166 | A 50-234 | A 50-311 | A 50-2024 | A 50-2209 | A 52-139 | K 50 L 3164 | K 50 P 1346 | K 50 P 1538 |
| A 50-167 | A 50-235 | A 50-316 | A 50-2025 | A 50-2211 | A 52-140 | K 50 L 3168 | K 50 P 1350 | K 50 P 1539 |
| A 50-169 | A 50-237 | A 50-317 | A 50-2026 | A 50-2213 | A 52-143 | K 50 L 3183 | K 50 P 1355 | K 50 P 1551 |
| A 50-170 | A 50-238 | A 50-321 | A 50-2027 | A 50-2214 | A 52-144 | K 50 L 3192 | K 50 P 1363 | |

VF 103

(K 50-H 1106/A 50-2125 B) kann als Ersatzregler für nachstehende Typen verwendet werden:

| | | | | | | | | |
|----------|-----------|-----------|-----------|-------------|-------------|-------------|-------------|-------------|
| A 50-198 | A 50-302 | A 50-2044 | A 50-2203 | A 52-2003 | K 50 H 2027 | K 50 L 3137 | K 50 L 3270 | K 50 P 1358 |
| A 50-203 | A 50-307 | A 50-2048 | A 50-2210 | A 52-2004 | K 50 H 2028 | K 50 L 3139 | K 50 L 3281 | K 50 P 1361 |
| A 50-204 | A 50-308 | A 50-2049 | A 50-2219 | A 52-2005 | K 50 H 2058 | K 50 L 3145 | K 50 L 3282 | K 50 P 1372 |
| A 50-207 | A 50-315 | A 50-2050 | A 50-2276 | A 52-2006 | K 50 L 3000 | K 50 L 3148 | K 50 L 3296 | K 50 P 1376 |
| A 50-212 | A 50-319 | A 50-2052 | A 50-2278 | A 52-2007 | K 50 L 3033 | K 50 L 3149 | K 50 L 3298 | K 50 P 1378 |
| A 50-214 | A 50-526 | A 50-2053 | A 50-2279 | A 52-2008 | K 50 L 3034 | K 50 L 3151 | K 50 L 3320 | K 50 P 1387 |
| A 50-215 | A 50-527 | A 50-2058 | A 50-2281 | A 52-2009 | K 50 L 3037 | K 50 L 3154 | K 50 L 3321 | K 50 P 1391 |
| A 50-218 | A 50-533 | A 50-2062 | A 50-2282 | A 52-2010 | K 50 L 3040 | K 50 L 3159 | | K 50 P 1392 |
| A 50-219 | A 50-535 | A 50-2063 | A 50-2283 | A 52-2013 | K 50 L 3043 | K 50 L 3160 | K 50 P 1126 | K 50 P 1404 |
| A 50-229 | A 50-542 | A 50-2067 | A 50-2285 | A 52-2014 | K 50 L 3050 | K 50 L 3173 | K 50 P 1128 | K 50 P 1411 |
| A 50-236 | A 50-553 | A 50-2104 | A 50-2289 | A 52-2015 | K 50 L 3057 | K 50 L 3174 | K 50 P 1129 | K 50 P 1420 |
| A 50-246 | A 50-558 | A 50-2109 | A 50-2293 | A 52-2016 | K 50 L 3060 | K 50 L 3177 | K 50 P 1139 | K 50 P 1428 |
| A 50-248 | A 50-1002 | A 50-2114 | A 50-2306 | A 52-2017 | K 50 L 3072 | K 50 L 3178 | K 50 P 1140 | K 50 P 1436 |
| A 50-249 | A 50-2001 | A 50-2117 | A 50-2310 | A 52-2019 | K 50 L 3075 | K 50 L 3181 | K 50 P 1153 | K 50 P 1449 |
| A 50-254 | A 50-2006 | A 50-2120 | A 50-2360 | A 52-2020 | K 50 L 3099 | K 50 L 3186 | K 50 P 1167 | K 50 P 1455 |
| A 50-259 | A 50-2009 | A 50-2136 | A 52-114 | A 52-2021 | K 50 L 3101 | K 50 L 3188 | K 50 P 1172 | K 50 P 1466 |
| A 50-261 | A 50-2010 | A 50-2138 | A 52-123 | K 50 H 1102 | K 50 L 3102 | K 50 L 3189 | K 50 P 1182 | K 50 P 1474 |
| A 50-226 | A 50-2011 | A 50-2139 | A 52-130 | K 50 H 1103 | K 50 L 3103 | K 50 L 3197 | K 50 P 1189 | K 50 P 1475 |
| A 50-266 | A 50-2013 | A 50-2141 | A 52-136 | K 50 H 1127 | K 50 L 3110 | K 50 L 3214 | K 50 P 1226 | K 50 P 1505 |
| A 50-269 | A 50-2018 | A 50-2152 | A 52-152 | K 50 H 1130 | K 50 L 3112 | K 50 L 3237 | K 50 P 1252 | K 50 P 1515 |
| A 50-277 | A 50-2031 | A 50-2153 | A 52-154 | K 50 H 1132 | K 50 L 3118 | K 50 L 3242 | K 50 P 1253 | |
| A 50-285 | A 50-2032 | A 50-2155 | A 52-171 | K 50 H 2000 | K 50 L 3123 | K 50 L 3257 | K 50 P 1262 | |
| A 50-286 | A 50-2039 | A 50-2156 | A 52-2000 | K 50 H 2009 | K 50 L 3127 | K 50 L 3258 | K 50 P 1267 | |
| A 50-287 | A 50-2042 | A 50-2164 | A 52-2001 | K 50 H 2023 | K 50 L 3132 | K 50 L 3262 | K 50 P 1351 | |
| A 50-298 | A 50-2043 | A 50-2126 | A 52-2002 | K 50 H 2026 | K 50 L 3134 | K 50 L 3263 | K 50 P 1354 | |

VB 107

(K 50-H 1107/A 50-2126 B) kann als Ersatzregler für nachstehende Typen verwendet werden:

| | | | | | | | | |
|-----------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| A 50-154 | A 50-2151 | K 50 H 1135 | K 50 L 3053 | K 50 L 3176 | K 50 L 3260 | K 50 P 1130 | K 50 P 1389 | K 50 P 1511 |
| A 50-165 | A 50-2169 | K 50 H 2012 | K 50 L 3081 | K 50 L 3182 | K 50 L 3268 | K 50 P 1141 | K 50 P 1390 | K 50 P 1513 |
| A 50-205 | A 50-2295 | K 50 H 2021 | K 50 L 3082 | K 50 L 3185 | K 50 L 3269 | K 50 P 1142 | K 50 P 1400 | K 50 P 1524 |
| A 50-245 | A 50-3202 | K 50 H 2029 | K 50 L 3083 | K 50 L 3195 | K 50 L 3276 | K 50 P 1143 | K 50 P 1407 | K 50 P 1527 |
| A 50-320 | A 52-108 | K 50 H 2040 | K 50 L 3096 | K 50 L 3198 | K 50 L 3283 | K 50 P 1188 | K 50 P 1429 | K 50 P 1533 |
| A 50-540 | A 52-118 | K 50 H 2044 | K 50 L 3100 | K 50 L 3212 | K 50 L 3284 | K 50 P 1261 | K 50 P 1432 | K 50 P 1535 |
| A 50-550 | A 52-141 | K 50 H 2047 | K 50 L 3114 | K 50 L 3220 | K 50 L 3288 | K 50 P 1356 | K 50 P 1435 | K 50 P 1536 |
| A 50-560 | A 52-149 | K 50 H 2059 | K 50 L 3122 | K 50 L 3222 | K 50 L 3295 | K 50 P 1357 | K 50 P 1440 | K 50 P 1541 |
| A 50-1000 | A 52-167 | K 50 H 2061 | K 50 L 3129 | K 50 L 3223 | K 50 L 3302 | K 50 P 1360 | K 50 P 1454 | K 50 P 1542 |
| A 50-2045 | A 52-169 | K 50 L 1367 | K 50 L 3130 | K 50 L 3229 | K 50 L 3304 | K 50 P 1362 | K 50 P 1457 | K 50 P 1544 |
| A 50-2051 | A 52-181 | K 50 L 3001 | K 50 L 3142 | K 50 L 3239 | K 50 L 3319 | K 50 P 1369 | K 50 P 1468 | K 50 P 1548 |
| A 50-2128 | | K 50 L 3004 | K 50 L 3152 | K 50 L 3246 | K 50 L 3332 | K 50 P 1370 | K 50 P 1471 | K 50 P 1549 |
| A 50-2135 | K 50 H 1114 | K 50 L 3005 | K 50 L 3155 | K 50 L 3251 | K 50 L 3335 | K 50 P 1385 | K 50 P 1501 | K 50 P 1555 |
| A 50-2148 | K 50 H 1124 | K 50 L 3019 | K 50 L 3171 | K 50 L 3253 | K 50 P 1118 | K 50 P 1386 | K 50 P 1509 | |

VI 109

(K 59-H 1303/A 59-1016 B) kann als Ersatzregler für nachstehende Typen verwendet werden:

| | | | | | | | | |
|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| A 59-0104 | K 59 L 1114 | K 59 L 1251 | K 59 L 2526 | K 59 L 4070 | K 59 P 1652 | K 59 P 1733 | K 59 P 3135 | K 59 P 4900 |
| A 59-1017 | K 59 L 1128 | K 59 L 1263 | K 59 L 2527 | K 59 L 4071 | K 59 P 1658 | K 59 P 1734 | K 59 P 3136 | K 59 P 4902 |
| A 59-1018 | K 59 L 1131 | K 59 L 1278 | K 59 L 2530 | K 59 L 4074 | K 59 P 1666 | K 59 P 1735 | K 59 P 3137 | K 59 P 4905 |
| A 59-1036 | K 59 L 1132 | K 59 L 1286 | K 59 L 2531 | K 59 L 4076 | K 59 P 1670 | K 59 P 1737 | K 59 P 3140 | K 59 P 4907 |
| A 59-5504 | K 59 L 1134 | K 59 L 1287 | K 59 L 2532 | K 59 L 4077 | K 59 P 1672 | K 59 P 1738 | K 59 P 4802 | K 59 P 4915 |
| | K 59 L 1141 | K 59 L 1288 | K 59 L 2547 | K 59 L 4081 | K 59 P 1673 | K 59 P 1741 | K 59 P 4810 | K 59 P 4916 |
| K 59 H 1300 | K 59 L 1143 | K 59 L 1295 | K 59 L 2555 | K 59 L 4082 | K 59 P 1676 | K 59 P 1744 | K 59 P 4811 | K 59 P 4918 |
| K 59 H 1311 | K 59 L 1150 | K 59 L 1296 | K 59 L 2594 | K 59 L 4102 | K 59 P 1681 | K 59 P 1749 | K 59 P 4813 | K 59 P 4924 |
| K 59 H 1316 | K 59 L 1152 | K 59 L 1297 | K 59 L 2601 | K 59 L 4105 | K 59 P 1682 | K 59 P 1750 | K 59 P 4816 | K 59 P 4926 |
| K 59 H 1317 | K 59 L 1165 | K 59 L 1907 | K 59 L 2634 | K 59 L 6024 | K 59 P 1686 | K 59 P 1760 | K 59 P 4818 | K 59 P 4927 |
| K 59 H 1327 | K 59 L 1167 | K 59 L 1908 | K 59 L 2635 | K 59 L 6100 | K 59 P 1689 | K 59 P 1765 | K 59 P 4843 | K 59 P 4941 |
| K 59 H 1054 | K 59 L 1171 | K 59 L 1913 | K 59 L 2637 | K 59 P 1600 | K 59 P 1690 | K 59 P 1767 | K 59 P 4848 | K 59 P 4942 |
| K 59 H 1332 | K 59 L 1178 | K 59 L 1924 | K 59 L 2655 | K 59 P 1605 | K 59 P 1691 | K 59 P 1788 | K 59 P 4854 | K 59 P 4949 |
| K 59 H 1335 | K 59 L 1179 | K 59 L 1928 | K 59 L 4022 | K 59 P 1607 | K 59 P 1693 | K 59 P 3100 | K 59 P 4863 | K 59 P 4951 |
| K 59 H 1351 | K 59 L 1180 | K 59 L 1933 | K 59 L 4024 | K 59 P 1613 | K 59 P 1697 | K 59 P 3104 | K 59 P 4874 | K 59 P 4953 |
| K 59 L 1058 | K 59 L 1186 | K 59 L 1937 | K 59 L 4025 | K 59 P 1618 | K 59 P 1701 | K 59 P 3105 | K 59 P 4877 | K 59 P 4957 |
| K 59 L 1063 | K 59 L 1203 | K 59 L 1939 | K 59 L 4039 | K 59 P 1619 | K 59 P 1702 | K 59 P 3112 | K 59 P 4879 | K 59 P 4960 |
| K 59 L 1074 | K 59 L 1204 | K 59 L 1952 | K 59 L 4043 | K 59 P 1620 | K 59 P 1705 | K 59 P 3118 | K 59 P 4881 | K 59 P 4961 |
| K 59 L 1077 | K 59 L 1211 | K 59 L 1954 | K 59 L 4044 | K 59 P 1622 | K 59 P 1707 | K 59 P 3119 | K 59 P 4883 | K 59 P 6808 |
| K 59 L 1079 | K 59 L 1212 | K 59 L 1976 | K 59 L 4045 | K 59 P 1626 | K 59 P 1724 | K 59 P 3120 | K 59 P 4884 | K 59 P 6811 |
| K 59 L 1096 | K 59 L 1214 | K 59 L 1982 | K 59 L 4046 | K 59 P 1628 | K 59 P 1728 | K 59 P 3124 | K 59 P 4886 | K 59 P 6815 |
| K 59 L 1099 | K 59 L 1220 | K 59 L 1989 | K 59 L 4047 | K 59 P 1634 | K 59 P 1729 | K 59 P 3125 | K 59 P 4887 | K 59 P 6818 |
| K 59 L 1101 | K 59 L 1222 | K 59 L 1991 | K 59 L 4051 | K 59 P 1639 | K 59 P 1730 | K 59 P 3130 | K 59 P 4894 | |
| K 59 L 1104 | K 59 L 1226 | K 59 L 1999 | K 59 L 4052 | K 59 P 1640 | K 59 P 1731 | K 59 P 3133 | K 59 P 4897 | |
| K 59 L 1105 | K 59 L 1242 | K 59 L 2002 | K 59 L 4057 | K 59 P 1651 | K 59 P 1732 | K 59 P 3134 | K 59 P 4899 | |

VI 112

(K 59-H 2805 /A 59-1019 B)

kann als Ersatzregler für nachstehende Typen verwendet werden:

| | | | | | | | | |
|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| A 59-106 | K 59 H 1319 | K 59 L 1061 | K 59 L 1182 | K 59 L 1904 | K 59 L 2553 | K 59 L 4038 | K 59 P 1679 | K 59 P 4827 |
| A 59-107 | K 59 H 1321 | K 59 L 1064 | K 59 L 1184 | K 59 L 1905 | K 59 L 2554 | K 59 L 4040 | K 59 P 1680 | K 59 P 4828 |
| A 59-108 | K 59 H 1322 | K 59 L 1065 | K 59 L 1185 | K 59 L 1906 | K 59 L 2580 | K 59 L 4041 | K 59 P 1683 | K 59 P 4829 |
| A 59-109 | K 59 H 1323 | K 59 L 1066 | K 59 L 1187 | K 59 L 1910 | K 59 L 2582 | K 59 L 4044 | K 59 P 1684 | K 59 P 4833 |
| A 59-110 | K 59 H 1325 | K 59 L 1067 | K 59 L 1189 | K 59 L 1915 | K 59 L 2583 | K 59 L 4045 | K 59 P 1685 | K 59 P 4834 |
| A 59-111 | K 59 H 1343 | K 59 L 1068 | K 59 L 1190 | K 59 L 1918 | K 59 L 2586 | K 59 L 4049 | K 59 P 1687 | K 59 P 4844 |
| A 59-112 | K 59 H 1348 | K 59 L 1069 | K 59 L 1193 | K 59 L 1919 | K 59 L 2588 | K 59 L 4050 | K 59 P 1692 | K 59 P 4849 |
| A 59-116 | K 59 H 1349 | K 59 L 1070 | K 59 L 1194 | K 59 L 1920 | K 59 L 2589 | K 59 L 4053 | K 59 P 1694 | K 59 P 4851 |
| A 59-125 | K 59 H 2800 | K 59 L 1071 | K 59 L 1196 | K 59 L 1921 | K 59 L 2590 | K 59 L 4054 | K 59 P 1695 | K 59 P 4853 |
| A 59-1004 | K 59 H 2801 | K 59 L 1073 | K 59 L 1197 | K 59 L 1922 | K 59 L 2591 | K 59 L 4055 | K 59 P 1703 | K 59 P 4872 |
| A 59-1005 | K 59 H 2802 | K 59 L 1075 | K 59 L 1198 | K 59 L 1923 | K 59 L 2592 | K 59 L 4058 | K 59 P 1706 | K 59 P 4873 |
| A 59-1014 | K 59 H 2803 | K 59 L 1076 | K 59 L 1199 | K 59 L 1925 | K 59 L 2593 | K 59 L 4059 | K 59 P 1723 | K 59 P 4876 |
| A 59-1015 | K 59 H 2807 | K 59 L 1078 | K 59 L 1200 | K 59 L 1926 | K 59 L 2595 | K 59 L 4062 | K 59 P 1725 | K 59 P 4878 |
| A 59-1021 | K 59 H 2808 | K 59 L 1081 | K 59 L 1201 | K 59 L 1929 | K 59 L 2596 | K 59 L 4063 | K 59 P 1742 | K 59 P 4880 |
| A 59-1031 | K 59 H 2809 | K 59 L 1085 | K 59 L 1205 | K 59 L 1930 | K 59 L 2597 | K 59 L 4069 | K 59 P 1743 | K 59 P 4882 |
| A 59-1032 | K 59 H 2810 | K 59 L 1086 | K 59 L 1206 | K 59 L 1931 | K 59 L 2598 | K 59 L 4072 | K 59 P 1746 | K 59 P 4893 |
| A 59-1500 | K 59 H 2811 | K 59 L 1091 | K 59 L 1207 | K 59 L 1932 | K 59 L 2599 | K 59 L 4075 | K 59 P 1748 | K 59 P 4895 |
| A 59-1506 | K 59 H 2813 | K 59 L 1092 | K 59 L 1208 | K 59 L 1934 | K 59 L 2600 | K 59 L 4078 | K 59 P 1751 | K 59 P 4896 |
| A 59-1508 | K 59 H 2814 | K 59 L 1093 | K 59 L 1210 | K 59 L 1935 | K 59 L 2602 | K 59 L 4079 | K 59 P 1752 | K 59 P 4908 |
| A 59-1509 | K 59 H 2815 | K 59 L 1095 | K 59 L 1213 | K 59 L 1936 | K 59 L 2603 | K 59 L 4080 | K 59 P 1756 | K 59 P 4909 |
| A 59-1510 | K 59 H 2816 | K 59 L 1097 | K 59 L 1221 | K 59 L 1938 | K 59 L 2604 | K 59 L 4101 | K 59 P 1757 | K 59 P 4910 |
| A 59-1516 | K 59 H 2817 | K 59 L 1098 | K 59 L 1223 | K 59 L 1940 | K 59 L 2606 | K 59 L 4103 | K 59 P 1758 | K 59 P 4911 |
| A 59-2000 | K 59 H 2818 | K 59 L 1100 | K 59 L 1224 | K 59 L 1942 | K 59 L 2607 | K 59 L 4104 | K 59 P 1759 | K 59 P 4912 |
| A 59-2001 | K 59 H 2820 | K 59 L 1102 | K 59 L 1227 | K 59 L 1943 | K 59 L 2608 | K 59 L 4106 | K 59 P 1771 | K 59 P 4914 |
| A 59-2004 | K 59 H 2821 | K 59 L 1108 | K 59 L 1229 | K 59 L 1944 | K 59 L 2609 | K 59 L 8020 | K 59 P 1773 | K 59 P 4919 |
| A 59-2006 | K 59 H 2822 | K 59 L 1109 | K 59 L 1231 | K 59 L 1946 | K 59 L 2615 | K 59 L 8021 | K 59 P 1774 | K 59 P 4920 |
| A 59-2007 | K 59 H 2823 | K 59 L 1110 | K 59 L 1233 | K 59 L 1948 | K 59 L 2616 | K 59 L 8022 | K 59 P 1779 | K 59 P 4921 |
| A 59-2008 | K 59 H 2824 | K 59 L 1112 | K 59 L 1234 | K 59 L 1950 | K 59 L 2618 | K 59 L 8023 | K 59 P 1782 | K 59 P 4922 |
| A 59-2009 | K 59 H 2826 | K 59 L 1115 | K 59 L 1235 | K 59 L 1953 | K 59 L 2620 | K 59 L 8024 | K 59 P 1785 | K 59 P 4923 |
| A 59-2010 | K 59 H 2827 | K 59 L 1116 | K 59 L 1236 | K 59 L 1956 | K 59 L 2621 | K 59 L 8025 | K 59 P 1786 | K 59 P 4928 |
| A 59-6000 | K 59 H 2828 | K 59 L 1117 | K 59 L 1239 | K 59 L 1957 | K 59 L 2622 | K 59 L 8026 | K 59 P 1789 | K 59 P 4929 |
| A 59-6003 | K 59 H 2829 | K 59 L 1118 | K 59 L 1240 | K 59 L 1959 | K 59 L 2623 | K 59 L 8027 | K 59 P 3101 | K 59 P 4930 |
| A 59-6005 | K 59 H 2830 | K 59 L 1119 | K 59 L 1241 | K 59 L 1961 | K 59 L 2624 | K 59 P 1603 | K 59 P 3102 | K 59 P 4939 |
| A 59-6006 | K 59 H 2832 | K 59 L 1121 | K 59 L 1244 | K 59 L 1963 | K 59 L 2627 | K 59 P 1604 | K 59 P 3103 | K 59 P 4940 |
| A 59-6007 | K 59 H 2833 | K 59 L 1124 | K 59 L 1245 | K 59 L 1964 | K 59 L 2629 | K 59 P 1606 | K 59 P 3106 | K 59 P 4943 |
| A 59-6008 | K 59 H 2834 | K 59 L 1125 | K 59 L 1250 | K 59 L 1965 | K 59 L 2630 | K 59 P 1608 | K 59 P 3108 | K 59 P 4944 |
| A 59-6009 | K 59 H 2835 | K 59 L 1126 | K 59 L 1253 | K 59 L 1966 | K 59 L 2631 | K 59 P 1610 | K 59 P 3109 | K 59 P 4945 |
| A 59-6010 | K 59 H 2836 | K 59 L 1127 | K 59 L 1254 | K 59 L 1967 | K 59 L 2632 | K 59 P 1611 | K 59 P 3110 | K 59 P 4947 |
| A 59-6011 | K 59 H 2838 | K 59 L 1129 | K 59 L 1257 | K 59 L 1971 | K 59 L 2639 | K 59 P 1612 | K 59 P 3111 | K 59 P 4950 |
| A 59-8600 | K 59 H 2841 | K 59 L 1130 | K 59 L 1258 | K 59 L 1972 | K 59 L 2640 | K 59 P 1614 | K 59 P 3113 | K 59 P 4954 |
| A 59-8601 | K 59 L 1020 | K 59 L 1133 | K 59 L 1260 | K 59 L 1978 | K 59 L 2642 | K 59 P 1615 | K 59 P 3114 | K 59 P 4958 |
| A 59-8602 | K 59 L 1021 | K 59 L 1135 | K 59 L 1261 | K 59 L 1979 | K 59 L 2643 | K 59 P 1616 | K 59 P 3115 | K 59 P 4959 |
| A 59-8603 | K 59 L 1022 | K 59 L 1136 | K 59 L 1262 | K 59 L 1984 | K 59 L 2649 | K 59 P 1617 | K 59 P 3116 | K 59 P 6800 |
| A 59-8604 | K 59 L 1025 | K 59 L 1137 | K 59 L 1265 | K 59 L 1993 | K 59 L 2651 | K 59 P 1621 | K 59 P 3117 | K 59 P 6801 |
| A 59-8605 | K 59 L 1027 | K 59 L 1138 | K 59 L 1267 | K 59 L 1994 | K 59 L 2652 | K 59 P 1624 | K 59 P 3121 | K 59 P 6803 |
| A 59-8606 | K 59 L 1031 | K 59 L 1139 | K 59 L 1268 | K 59 L 1997 | K 59 L 2656 | K 59 P 1625 | K 59 P 3122 | K 59 P 6804 |
| A 59-8607 | K 59 L 1032 | K 59 L 1142 | K 59 L 1269 | K 59 L 1998 | K 59 L 2658 | K 59 P 1627 | K 59 P 3123 | K 59 P 6806 |
| A 59-8608 | K 59 L 1033 | K 59 L 1145 | K 59 L 1271 | K 59 L 2000 | K 59 L 2659 | K 59 P 1629 | K 59 P 3127 | K 59 P 6807 |
| A 59-8609 | K 59 L 1035 | K 59 L 1146 | K 59 L 1272 | K 59 L 2001 | K 59 L 2660 | K 59 P 1630 | K 59 P 3129 | K 59 P 6810 |
| | K 59 L 1040 | K 59 L 1149 | K 59 L 1273 | K 59 L 2003 | K 59 L 2663 | K 59 P 1631 | K 59 P 3139 | K 59 P 6816 |
| K 59 H 1301 | K 59 L 1041 | K 59 L 1151 | K 59 L 1274 | K 59 L 2005 | K 59 L 4020 | K 59 P 1632 | K 59 P 3145 | K 59 P 6817 |
| K 59 H 1302 | K 59 L 1042 | K 59 L 1154 | K 59 L 1277 | K 59 L 2007 | K 59 L 4021 | K 59 P 1642 | K 59 P 3146 | K 59 P 6820 |
| K 59 H 1304 | K 59 L 1043 | K 59 L 1159 | K 59 L 1279 | K 59 L 2010 | K 59 L 4023 | K 59 P 1643 | K 59 P 3147 | K 59 P 6821 |
| K 59 H 1305 | K 59 L 1047 | K 59 L 1160 | K 59 L 1281 | K 59 L 2522 | K 59 L 4024 | K 59 P 1644 | K 59 P 3148 | K 59 P 6824 |
| K 59 H 1306 | K 59 L 1048 | K 59 L 1164 | K 59 L 1282 | K 59 L 2523 | K 59 L 4026 | K 59 P 1650 | K 59 P 3150 | K 59 P 6825 |
| K 59 H 1307 | K 59 L 1049 | K 59 L 1166 | K 59 L 1283 | K 59 L 2528 | K 59 L 4029 | K 59 P 1653 | K 59 P 3151 | K 59 P 6827 |
| K 59 H 1308 | K 59 L 1050 | K 59 L 1168 | K 59 L 1285 | K 59 L 2529 | K 59 L 4030 | K 59 P 1654 | K 59 P 3152 | K 59 P 6829 |
| K 59 H 1309 | K 59 L 1051 | K 59 L 1169 | K 59 L 1290 | K 59 L 2533 | K 59 L 4031 | K 59 P 1657 | K 59 P 4800 | |
| K 59 H 1310 | K 59 L 1052 | K 59 L 1170 | K 59 L 1292 | K 59 L 2539 | K 59 L 4032 | K 59 P 1660 | K 59 P 4801 | |
| K 59 H 1312 | K 59 L 1053 | K 59 L 1172 | K 59 L 1293 | K 59 L 2541 | K 59 L 4033 | K 59 P 1661 | K 59 P 4803 | |
| K 59 H 1313 | K 59 L 1055 | K 59 L 1173 | K 59 L 1298 | K 59 L 2543 | K 59 L 4034 | K 59 P 1663 | K 59 P 4804 | |
| K 59 H 1314 | K 59 L 1056 | K 59 L 1174 | K 59 L 1299 | K 59 L 2545 | K 59 L 4035 | K 59 P 1667 | K 59 P 4812 | |
| K 59 H 1315 | K 59 L 1059 | K 59 L 1175 | K 59 L 1900 | K 59 L 2546 | K 59 L 4036 | K 59 P 1671 | K 59 P 4815 | |
| K 59 H 1318 | K 59 L 1060 | K 59 L 1176 | K 59 L 1901 | K 59 L 2552 | K 59 L 4037 | K 59 P 1678 | K 59 P 4817 | |